

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080124-6

No. 11059

RECEIVED FROM

Plant #9

DATE REC'D. 1-2-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. PART OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.
1	322	000000	738319-2 22093 Bearing Retainer							
	DRAWING NO. AND DESCRIPTION						QUANTITY		REMARKS	
							ACCEPTED	REJECTED		
	10 superseded 311029						1 ✓			

W. P. Parker
D. E. Parker

RECEIVED BY
HMC-1089

INSPECTED BY

Date

DATE 1-28-57

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2751 E. COLORADO ST., PASADENA, CALIF.

No. 11064

RECEIVED FROM

Plant #9

DATE REC'D. 1-2-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. PART OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.
1	322	000000	738263 Wiring Assy							
	DRAWING NO. AND DESCRIPTION						QUANTITY		REMARKS	
							ACCEPTED	REJECTED		
	10 superseded 31101						1 ✓			

W. P. Parker
D. E. Parker

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080124-6

RECEIVED BY

HMC-1089

Date

DATE 1-28-57

REJECTS RETURNED